LQS report

Paolo Ferracin

LARP Collaboration Meeting FNAL October 27, 2008



Outline

- Task goals
- Magnet design and assembly procedure
- Magnetic and mechanical analysis
- Assembly, loading, and cool-down of a 850 mm long segment with dummy coils
- Assembly of full-length shell-yoke sub-assembly
- Conclusions and next steps




Task goals

- Mechanical and magnetic analysis of LQS01
- Engineering design and procurement of support structure and handling, lifting, and tilting tooling
- Assembly, loading, and cool-down to 77 K of
 - 850 mm long segment with dummy coils
 - Full-length structure with dummy coils
- Assembly, load, and test of LQS01



Magnet design Cross-section


- 20 mm thick Al shell
- 4-split iron yoke
 - Gap keys and auxiliary bladders
 - Holes for tie rods
- Iron pads
 - Holes for coil end support and tie rods
- Iron masters
 - 2 bladders
 - 2 interference keys
- G10 sheet between coil and pad laminations





Magnet design 3D components


- 4 shell segments, 0.85 m long
- Yoke laminations, 50 mm thick with 3.4 m long tie rods
- Iron pad laminations, 50 mm thick with 3.4 m long tie rods
- Iron masters, 2 x 1.7 m long
 - Easy insertion and removal of coil pack (large clearance)
 - Continuous surface
 - Pad-yoke alignment
 - Improved tolerances





Assembly procedure

- Alignment of pad and yoke laminations with bushings
 - Insertion of tie rods
 - Pre-tension with piston
- Assembly of 850 mm long segments
- Joining of segments with air pallets
 - Alignment by shell-yoke pins
- Insertion of coil-pad subassembly with masters






2D magnetic analysis

- J_c of 2800 A/mm² (4.2 K, 12 T)
- About 2 T difference between layer 1 and layer 2


30.0	_						
28.0	_						
26.0					_		
24.0							
22.0	-						
20.0	- 😽		· ·			<u>l</u>	
18.0	_						
16.0	_ '					4	
14.0	_						
12.0	_						
10.0	_			4			
8.0				-			
6.0	_						
4.0	_						
2.0							
L	40.0	45.0	50.0	55.0	60.0	65.0	_

			Layer 1	Layer 2	
Temp.	Current	Gradient	Peak field	Peak field	Stored energy
K	kA	T/m	Т	Т	kJ/m
4.5	13.76	240	12.29	10.52	457
1.9	15.16	262	13.43	11.48	559



3D magnetic analysis


- Peak field in the end located on pole turn, layer 1
- Stainless steel pad 100 mm





2D mechanical analysis

- No gap pole-coil at 240 T/m
- Coil peak stress at 4.5 K
 - Pole area, inner radius, layer 1
 - 171 MPa
- Coil peak stress at 240 T/m
 - Mid-plane, inner radius, layer 1
 - 168 MPa
- Key position optimized to minimize coil stress after cool-down and at 240 T/m
- <150 MPa of coil peak stress assuming 220 T/m





3D mechanical analysis


No gap pole-coil at 240 T/m


Axial e.m. force: 471 kN

Stainless steel rod pre-tension: 88 MPa (178 kN)

Rod stress at 4.5 K: 239 MPa (484 kN)

65 MPa of contact press. after cool-down







Outline

- Task goals
- Magnet design and assembly procedure
- Magnetic and mechanical analysis
- Assembly, loading, and cool-down of a 850 mm long segment with dummy coils
- Assembly of full-length shell-yoke sub-assembly
- Conclusions and next steps



Assembly and loading of 850 mm long segment Stacking pad and yoke laminations







Yoke rod tension: 330 MPa

Force on yoke stack: 190 kN



Assembly and loading of 850 mm long segment Insertion of yoke stacks in shell









Assembly and loading of 850 mm long segment Assembly of dummy coil pack







Assembly and loading of 850 mm long segment Loading and insertion in the cryostat








Cool-down to 77 K of 850 mm long segment

- Shell stress at 77 K
 - Azimuthal: +138 ± 6 MPa
 - Axial: +41 ± 13 MPa

- Dummy coil stress at77K
 - Azimuthal: -231 ± 23 MPa
 - Axial: +74 ± 7 MPa





Assembly of full-length structure Section 1 and 2 before joining operation





Assembly of full-length structure Removal of 850 mm long yoke tie rods







Assembly of full-length structure Preparation of alignment pins and bushings







Assembly of full-length structure Joining operation of 2 segments (I)












Assembly of full-length structure Joining operation of 2 segments (II)







Assembly of full-length structure Insertion-tensioning of 1.7 m long yoke tie rods





Assembly of full-length structure Assembly of 1.7 m long dummy coil pack








Assembly of full-length structure Pre-loading and insertion of 1.7 m long gap keys














Assembly of full-length structure Assembly of second segment pair






Assembly of full-length structure Joining operation of 2 segment pairs











Assembly of full-length structure 3.4 m long yoke-shell sub-assembly





Assembly of full-length structure 3.4 m long yoke-shell sub-assembly





Outline

- Task goals
- Magnet design and assembly procedure
- Magnetic and mechanical analysis
- Assembly, loading, and cool-down of a 850 mm long segment with dummy coils
- Assembly of full-length shell-yoke sub-assembly
- Conclusions and next steps



Conclusions

- 3.7 m long LQ shell-based support structure (LQS) designed, analyzed with 2D/3D magnetic/mechanical models, and procured
 - Coil supported (no gaps expected) up to 240 T/m
- 850 mm long segment assembled, loaded, and cooled-down to 77 K with dummy coils
 - Strain gauge results consistent with expectations
- Loading with bladders of a 1.7 m long structure performed
 - Same operation as for full-length structure
- Full-length shell-yoke sub-assembly completed
 - Successful implementation of procedure based on short segments



Next steps (I)


- Assembly of a full-length dummy coil pack
- Assembly and loading of a full-length structure with dummy coils (LQSD)
 - Bladder operation
 - Pressure sensitive film test
 - Pre-tensioning of coil axial support system






Next steps (II)

- Lifting/tilting tooling
 - Complete procurement
 - Test components
 - Assembly around LQSD structure




- Shipment LQSD from LBNL to FNAL
- Tilting and insertion in the cryostat
- Cool-down test of LQSD and analysis
- Shipment LQSD from FNAL to LBNL
- Disassembly of LQSD





Next steps (III)

- Tooling for coil-pad assembly
 - Complete design and procurement
 - Test with practice coils



- Assembly and loading of LQS01
 - Bladder and axial loading operations
 - Connection of all instrumentation to connectors mounted on the shell (lead end)
 - Assembly of lifting/tilting tooling
- Shipment of LQS01 from LBNL to FNAL
- Tilting and insertion of LQS01 in the cryostat
- Test of LQS01

